

CP-TOUCH

Release Notes

Revision: 1.5.4

2017-08-10

1 Introduction

This document contains information about software releases for the CP-TOUCH (21568) product. The release note is cumulative, each chapter describing changes since the previous released version.

2 Release 1.5.4 (U)

Release date : 2017-08-10

Panel firmware : cptouch-1.5.4.bin

Build number : 211

2.1 Corrections

- Fixed issue with wrong button status from data routers

3 Release 1.5.3 (T)

Release date : 2017-05-12

Panel firmware : cptouch-1.5.3.bin

Build number : 207

3.1 Corrections

- Fixed issue with lock/protect symbols on destination category index buttons
- Fixed issue with lock/protect symbols not visible in list views

4 Release 1.5.2 (S)

Release date : 2016-12-02

Panel firmware : cptouch-1.5.2.bin

Build number : 202

4.1 Corrections

- Fixed issue with reading DIP switches correctly

5 Release 1.5.1 (R)

Release date : 2016-11-17

Panel firmware : cptouch-1.5.1.bin

Build number : 200

5.1 Corrections

- Fixed issue where IP address was lost during reboot or reconfiguration

6 Release 1.5.0 (P)

Release date : 2016-10-31

Panel firmware : cptouch-1.5.0.bin

Build number : 197

6.1 New features

- Support for new CP-TOUCH mkII panels

7 Release 1.4.3 (N)

Release date : 2016-05-09

Panel firmware : cptouch-1.4.3.bin

Build number : 190

7.1 New features

- Added support for show virtual breakaway status config option

7.2 Corrections

- Fixed button colors on MEC-buttons
- Fixed handling of string parameters on MRP

8 Release 1.4.2 (M)

Release date : 2015-09-02

Panel firmware : cptouch-1.4.2.bin

Build number : 172

8.1 Corrections

- Fixed issue with virtual source buttons not being highlighted
- Fixed issue with list view making panel restart
- Fixed issue with list view and Lock/Protect buttons
- Fixed issue with list view not showing Lock/Protect values
- Fixed issue with list view not showing correct decimal values for parameters
- Fixed issue with take and salvo buttons
- Fixed issue with take and virtual categories

9 Release 1.4.1 (L)

Release date : 2015-03-30

Panel firmware : cptouch-1.4.1.bin

Build number : 165

9.1 Improvements

- Added support for button display mode on output, in2out, destination and src2dest buttons

9.2 Corrections

- Fixed issue with breakaway status on layouts with categories
- Fixed issue with src/dest index on layouts with advanced categories
- Fixed issue with panel display mode name/alias

10 Release 1.4.0 (K)

Release date : 2015-01-23

Panel firmware : cptouch-1.4.0.bin

Build number : 149

New feature:

- Added support for Include-In-Virtual-Level-Status feature

10.1 Improvements

- Virtual sources sends command when pushed in breakaway state
- Virtual destinations shows correct status when source is unknown
- Parameter values are shown without name in listview

10.2 Corrections

- Fixed issue with Virtual level toggle buttons not visible

11 Release 1.3.0 (J)

Release date : 2014-11-11

Panel firmware : cptouch-1.3.0.bin

Build number : 136

11.1 New features

- Added support for Advanced Category Control

11.2 Improvements

- Improved reconnect handling when losing IP connectivity
- Improved performance when switching layouts

11.3 Corrections

- Fixed issue with 20 button layouts, resulting in panel stopped working
- Fixed issue with multiple selection of category select buttons
- Fixed issue with category buttons activated after reboot

12 Release 1.2.1 (H)

Release date : 2014-04-09

Panel firmware : cptouch-1.2.1.bin

12.1 Improvements

- Improved longterm stability when performing layout switching

13 Release 1.2.0 (G)

Release date : 2013-10-30

Panel firmware : cptouch-1.2.0.bin

13.1 New features

- Added support for 20 buttons layout

13.2 Corrections

- Category select buttons are now highlighted when active
- Fixed take handling, preventing multiple buttons to be active

14 Release 1.1.1 (F)

Release date : 2013-07-02

Panel firmware : cptouch-1.1.1.bin

14.1 Corrections

- Scrolling on advanced level control
- Change of user does not require reboot
- Improved connection handling when Multicon restarts

15 Release 1.1.0 (E)

Release date : 2013-05-08

Panel firmware : cptouch-1.1.0.bin

15.1 New features

- Added support for virtual category control
- Added support for SourceToDest buttons

15.2 Corrections

- Fixed error when name changes occur on MRP protocol

16 Release 1.0.5 (D)

Release date : 2013-02-19

Panel firmware : cptouch-1.0.5.bin

16.1 New features

- Added support for multi-source status on virtual destinations
- Added support for In2Out buttons

16.2 Corrections

- Fixed state problem first time list views are shown
- Fixed minor issues with Take functionality
- Fixed list order for virtual sources and destinations in listviews/adv. control
- Fixed salvo restore problem on GPI, was not able to restore to fixed salvo
- Fixed initial state on GPI outputs, state was not set after reboot

17 Release 1.0.4 (3)

Release date : 2012-11-23

Panel firmware : cptouch-1.0.4.bin

17.1 New features

- Added support for GPI inputs and outputs
- Added support for custom level breakaway button

17.2 Improvements

- Take functionality needs to handle different layouts
- Update lock and protect buttons with correct button status & text

17.3 Corrections

- Take and Take On/Off is not working in virtual button configs
- Panel enable colors are not configurable
- Virtual routers are not controllable in listview
- Active input button is dimmed when other panels control same output
- Wrong system name in system menu
- Panel must be enabled when starting up without panel enable button
- Virtual Router Advanced control - destination buttons are fixed to red color
- Panel stops updating display after config change

18 Release 1.0.3 (2)

Release date : 2012-08-16 Panel firmware : cptouch-1.0.3.bin

18.1 Corrections

- Fixed startup sequence on panel, it sometimes doesn't start up
- Fixed lock and protect pictures on buttons

19 Release 1.0.1 (1)

Release date : 2012-08-07

Panel firmware : cptouch-1.0.1.bin

- Initial release of firmware.